



DEPARTMENT OF
WATER RESOURCES

DELTA AREA *Fact Sheet* **Site 20.8**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento River

River Mile: 20.8

Latitude/Longitude:

38.192364/-121.566679

Nearest Impact Area: Isleton

County: Sacramento

Bank: Left



Type of Damage

Bank erosion

Length of Repair


660 feet
(approximate)

Repair Type

Rock slope protection

Lead Agency

Department of
Water Resources



For further information,
please contact:

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov